

Sino Iron Case Study: Changing from Composite PE liner system to BGM liner system

Liza du Preez, Riaan Herbert – WSP Golder (Perth)

GEOANZ #1 ADVANCES IN GEOSYNTHETICS
7-9 JUNE 2022 | BRISBANE CONVENTION & EXHIBITION CENTRE

Structure

- Introduction
- Background
- Design
- Embankment cross section
- GCL / LLDPE Liner Installation
- Transition from GCL/LLDPE to BGM
- Construction of GCL/LLDPE BGM transition
- BGM Liner Installation
- Summary

Introduction

- Sino Iron Largest magnetite mining and processing operation, Australia
- Approximately 80 km south-west of Karratha




Background

• Downstream embankment construction using ROM waste rock from pit excavation.

ROM materials generally coarse and angular in nature containing

some fines from Yandi shales.

 Low permeability highly weathered overburden material used as secondary embankment material along upstream slopes (C2).



Design

- Thickened tailings disposal up to RL28.8 liner consisting of clayey material
- Changed to a paddock dumping system → supernatant pond relocated next to the external embankment
- Construction material up to RL28.8 of a granular nature → excessive seepage
- Requirement for improved liner system identified


Design – continued

Raise	Slope	Liner System
Up to RL28.8	1V:3H	C2 / Clayey Fill
RL28.8 to RL33	1V:3H	C2 / GCL / LLDPE
RL33 to RL39	1V:2.5H	C2 / GCL / LLDPE
RL39 to RL45	1V:1.3H	C2 / BGM liner system
RL45 to RL51	1V:1.3H	C2 / BGM liner system
RL51 to RL61	1V:1.3H	C2 / BGM liner system

Design — continued





RL28.8





1:3


GCL / LLDPE Liner Installation



































BGM Liner Installation



BGM Liner Installation



Summary

- GCL/LLDPE suitable for flatter slopes
- BGM has worked well on steep slopes despite the H&S challenges
- Transition between LLDPE and BGM is tricky and the installation method is difficult to get right
- Experienced contractors required